

 **DEMOLITION FLOOR PLAN – MECHANICAL PIPING**  
SCALE: 3/16" = 1'-0"

**ASBESTOS AND LEAD PAINT NOTE**

AN ASBESTOS INSPECTION WAS PERFORMED AND ASBESTOS CONTAINING MATERIALS WERE FOUND GENERALLY IN THE AREAS INDICATED IN THE ASBESTOS SURVEY/INSPECTION REPORT WHICH IS AVAILABLE TO THE CONTRACTOR(S) FOR HIS INFORMATION. ASBESTOS CONTAINING MATERIALS HAVE BEEN REMOVED UNDER A SEPARATE CONTRACT.

A LEAD-BASED PAINT INSPECTION WAS PERFORMED AND LEAD-BASED PAINT WAS FOUND IN THE AREAS INDICATED. THE CONTRACTOR SHALL BE RESPONSIBLE WITH ALL REQUIREMENTS OF THE VIRGINIA OCCUPATIONAL SAFETY AND HEALTH ADMINISTRATION REGULATIONS LEAD-BASED PAINT PROTECTION OF WORKERS.



**GRAPHIC SCALES**




**nbij** ARCHITECTURE  
A Professional Limited Company  
GROVE PARK SQUARE  
11537-B NUCKOLS ROAD  
Richmond, Virginia 23069  
☎ (804) 273-9611 fax: (804) 273-9843



**RAPPAHANNOCK  
COMMUNITY COLLEGE**  
CAMPUS RENOVATIONS  
WARSAW + GLENN, VIRGINIA  
PC: 260-17712

**GLENN CAMPUS  
DEMOLITION FLOOR  
PLAN – MECHANICAL PIPING**

Date:	JANUARY 13, 2010
REVISIONS	
NO.	DATE



Sheet  
**MD2.5G**  
File Number  
XX